


Ken Bauer INC.

277 Broadway, Hillsdale, NJ 07642
(201) 664-6881 www.kenbauer.com

Draw an outline of your room. Measure in inches. Start from a corner and work around the walls. Measure up to the trim of windows and doors. When measuring windows and doors, include the trim.

***Please take pictures on your phone of each wall to help verify the measurements.**

We do not need to know the location of your current cabinets. The measurements do not have to be exact to get an exact price. We will go measure if you go ahead with the job.



YOU CAN EMAIL YOUR MEASUREMENTS TO US IN ADVANCE AT KENBAUERINC@GMAIL.COM. PLEASE INCLUDE YOUR NAME AND PHONE NUMBER.

Showroom Hours

Monday, Wednesday, Friday	9:00am-4:30pm
Tuesday & Thursday	9:00am-8:30pm
Saturday	9:00am-3:00pm

PLEASE CALL TO MAKE AN APPOINTMENT